



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/SIR/QAR13.0018/10	Page 1 of 2
QAR Free Ref. No.:	80142230-80142231-80142232	Status: Issued
Details of change:	Recertification Audit	Date of issue: 2022-12-02
Site(s) audited:	Raytec Limited Unit 15 Wansbeck Business Park Rotary Parkway Ashington Northumberland NE63 8QW United Kingdom	Valid until: 2026-01-07 Audit date: 2022-11-07
Issuing ExCB:	CSAE - CSA Group Testing UK Ltd	
Manufacturer:	Raytec Limited Unit 15 Wansbeck Business Park Rotary Parkway Ashington Northumberland NE63 8QW	
Location of Manufacturer:	United Kingdom	
Product information:	Luminaires, Lamps and Accessories	
Protection concept:	Ex e, m, t, d, nR, ia	
Related QARs:		
GB/SIR/QAR13.0018/00	GB/SIR/QAR13.0018/01	GB/SIR/QAR13.0018/02
GB/SIR/QAR13.0018/03	GB/SIR/QAR13.0018/04	GB/SIR/QAR13.0018/05
GB/SIR/QAR13.0018/06	GB/SIR/QAR13.0018/07	GB/SIR/QAR13.0018/08
GB/SIR/QAR13.0018/09		

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEX CML 14.0001 issue: 0	IECEX CML 14.0001 issue: 1	IECEX CML 14.0001 issue: 2
IECEX CML 14.0001 issue: 3	IECEX CML 14.0001 issue: 4	IECEX CML 14.0001 issue: 5
IECEX CML 14.0001 issue: 6	IECEX CML 14.0001 issue: 7	IECEX CML 14.0001 issue: 8
IECEX CML 14.0001 issue: 9	IECEX CML 14.0001 issue: 10	IECEX CML 14.0001 issue: 11
IECEX CML 14.0001 issue: 12	IECEX CML 14.0001 issue: 13	IECEX CML 14.0001 issue: 14
IECEX CML 15.0001 issue: 0	IECEX CML 15.0001 issue: 1	IECEX CML 15.0001 issue: 2
IECEX CML 15.0001 issue: 3	IECEX CML 15.0001 issue: 4	IECEX CML 15.0001 issue: 5
IECEX CML 15.0001 issue: 6	IECEX CML 15.0001 issue: 7	IECEX CML 15.0001 issue: 8
IECEX CML 15.0001 issue: 9	IECEX CML 15.0001 issue: 10	IECEX CML 15.0001 issue: 11
IECEX CML 15.0001 issue: 12	IECEX CML 15.0001 issue: 13	IECEX CML 15.0068 issue: 0
IECEX CML 15.0068 issue: 1	IECEX CML 15.0068 issue: 2	IECEX CML 15.0068 issue: 3
IECEX CML 15.0068 issue: 4	IECEX CML 15.0068 issue: 5	IECEX CML 15.0068 issue: 6
IECEX CML 15.0068 issue: 7	IECEX CML 15.0068 issue: 8	IECEX CML 15.0068 issue: 9
IECEX CML 15.0068 issue: 10	IECEX CML 16.0052 issue: 0	IECEX CML 16.0052 issue: 1
IECEX CML 16.0052 issue: 2	IECEX CML 16.0052 issue: 3	IECEX CML 16.0052 issue: 4
IECEX CML 16.0052 issue: 5	IECEX CML 16.0052 issue: 6	IECEX CML 16.0052 issue: 7
IECEX CML 17.0074 issue: 0	IECEX CML 17.0074 issue: 1	IECEX CML 17.0074 issue: 2
IECEX CML 17.0074 issue: 3	IECEX CML 17.0120 issue: 0	IECEX CML 17.0120 issue: 1
IECEX CML 17.0135 issue: 0	IECEX CML 17.0135 issue: 1	IECEX CML 17.0135 issue: 2

-- Continued on the next page



IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR13.0018/10**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEx CML 18.0087 issue: 0
IECEx CML 21.0037 issue: 1

IECEx CML 18.0087 issue: 1
IECEx CML 21.0038 issue: 0

IECEx CML 21.0037 issue: 0
IECEx CML 21.0038 issue: 1

Comments: