



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR13.0018/12**

Page 1 of 2

QAR Free Ref. No.: **80187565/66/67**

Status: **Issued**

Details of change: **Surveillance Audit**

Date of issue: **2024-01-25**

Location(s) audited: **Raytec Limited**
Unit 15 Wansbeck Business Park
Rotary Parkway
Ashington
Northumberland
NE63 8QW
United Kingdom

Valid until: **2026-01-07**

Audit date: **2024-01-10**

Issuing ExCB: **CSAE - CSA Group Testing UK Ltd**

Manufacturer: **Raytec Limited**
Unit 15 Wansbeck Business Park
Rotary Parkway
Ashington
Northumberland
NE63 8QW

Location of
Manufacturer: **United Kingdom**

Product information: **Luminaires, Lamps and Accessories**

Type of protection: **Ex e, m, t, d, nR, ia**

Related QARs:

GB/SIR/QAR13.0018/00
GB/SIR/QAR13.0018/03
GB/SIR/QAR13.0018/06
GB/SIR/QAR13.0018/09

GB/SIR/QAR13.0018/01
GB/SIR/QAR13.0018/04
GB/SIR/QAR13.0018/07
GB/SIR/QAR13.0018/10

GB/SIR/QAR13.0018/02
GB/SIR/QAR13.0018/05
GB/SIR/QAR13.0018/08
GB/SIR/QAR13.0018/11

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEx CML 14.0001 issue: 0
IECEx CML 14.0001 issue: 3
IECEx CML 14.0001 issue: 6
IECEx CML 14.0001 issue: 9
IECEx CML 14.0001 issue: 12
IECEx CML 14.0001 issue: 15
IECEx CML 15.0001 issue: 2
IECEx CML 15.0001 issue: 5
IECEx CML 15.0001 issue: 8
IECEx CML 15.0001 issue: 11
IECEx CML 15.0001 issue: 14
IECEx CML 15.0068 issue: 2
IECEx CML 15.0068 issue: 5
IECEx CML 15.0068 issue: 8
IECEx CML 15.0068 issue: 11
IECEx CML 16.0052 issue: 2
IECEx CML 16.0052 issue: 5
IECEx CML 16.0052 issue: 8
IECEx CML 17.0074 issue: 2

IECEx CML 14.0001 issue: 1
IECEx CML 14.0001 issue: 4
IECEx CML 14.0001 issue: 7
IECEx CML 14.0001 issue: 10
IECEx CML 14.0001 issue: 13
IECEx CML 15.0001 issue: 0
IECEx CML 15.0001 issue: 3
IECEx CML 15.0001 issue: 6
IECEx CML 15.0001 issue: 9
IECEx CML 15.0001 issue: 12
IECEx CML 15.0068 issue: 0
IECEx CML 15.0068 issue: 3
IECEx CML 15.0068 issue: 6
IECEx CML 15.0068 issue: 9
IECEx CML 16.0052 issue: 0
IECEx CML 16.0052 issue: 3
IECEx CML 16.0052 issue: 6
IECEx CML 17.0074 issue: 0
IECEx CML 17.0074 issue: 3

IECEx CML 14.0001 issue: 2
IECEx CML 14.0001 issue: 5
IECEx CML 14.0001 issue: 8
IECEx CML 14.0001 issue: 11
IECEx CML 14.0001 issue: 14
IECEx CML 15.0001 issue: 1
IECEx CML 15.0001 issue: 4
IECEx CML 15.0001 issue: 7
IECEx CML 15.0001 issue: 10
IECEx CML 15.0001 issue: 13
IECEx CML 15.0068 issue: 1
IECEx CML 15.0068 issue: 4
IECEx CML 15.0068 issue: 7
IECEx CML 15.0068 issue: 10
IECEx CML 16.0052 issue: 1
IECEx CML 16.0052 issue: 4
IECEx CML 16.0052 issue: 7
IECEx CML 17.0074 issue: 1
IECEx CML 17.0074 issue: 4

-- Continued on the next page



IECEX Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR13.0018/12**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEX CML 17.0074 issue: 5
IECEX CML 17.0120 issue: 1
IECEX CML 17.0135 issue: 2
IECEX CML 18.0087 issue: 2
IECEX CML 21.0037 issue: 1
IECEX CML 23.0094X issue: 0

IECEX CML 17.0074 issue: 6
IECEX CML 17.0135 issue: 0
IECEX CML 18.0087 issue: 0
IECEX CML 18.0087 issue: 3
IECEX CML 21.0038 issue: 0

IECEX CML 17.0120 issue: 0
IECEX CML 17.0135 issue: 1
IECEX CML 18.0087 issue: 1
IECEX CML 21.0037 issue: 0
IECEX CML 21.0038 issue: 1

Comments: