



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR13.0018/09** Page 1 of 2
QAR Free Ref. No.: **80095943/44** Status: **Issued**
Details of change: **Surveillance Audit** Date of issue: **2022-01-19**
Site(s) audited: **Raytec Limited** Valid until: **2023-01-07**
Unit 15 Wansbeck Business Park
Rotary Parkway
Ashington
Northumberland
NE63 8QW
United Kingdom Audit date: **2021-10-19**

Issuing ExCB: **CSAE - CSA Group Testing UK Ltd**

Manufacturer: **Raytec Limited**
Unit 15 Wansbeck Business Park
Rotary Parkway
Ashington
Northumberland
NE63 8QW

Location of
Manufacturer: **United Kingdom**

Product information: **Luminaires, Lamps and Accessories**

Protection concept: **Ex e, m, t, d, nR, ia**

Related QARs:

GB/SIR/QAR13.0018/00	GB/SIR/QAR13.0018/01	GB/SIR/QAR13.0018/02
GB/SIR/QAR13.0018/03	GB/SIR/QAR13.0018/04	GB/SIR/QAR13.0018/05
GB/SIR/QAR13.0018/06	GB/SIR/QAR13.0018/07	GB/SIR/QAR13.0018/08

Related Certificates (manual insertion):

Related Certificates (automatic linking):

Related Certificates for
previous versions:

IECEX CML 14.0001 issue: 0	IECEX CML 14.0001 issue: 1	IECEX CML 14.0001 issue: 2
IECEX CML 14.0001 issue: 3	IECEX CML 14.0001 issue: 4	IECEX CML 14.0001 issue: 5
IECEX CML 14.0001 issue: 6	IECEX CML 14.0001 issue: 7	IECEX CML 14.0001 issue: 8
IECEX CML 14.0001 issue: 9	IECEX CML 14.0001 issue: 10	IECEX CML 14.0001 issue: 11
IECEX CML 14.0001 issue: 12	IECEX CML 14.0001 issue: 13	IECEX CML 14.0001 issue: 0
IECEX CML 15.0001 issue: 1	IECEX CML 15.0001 issue: 2	IECEX CML 15.0001 issue: 3
IECEX CML 15.0001 issue: 4	IECEX CML 15.0001 issue: 5	IECEX CML 15.0001 issue: 6
IECEX CML 15.0001 issue: 7	IECEX CML 15.0001 issue: 8	IECEX CML 15.0001 issue: 9
IECEX CML 15.0001 issue: 10	IECEX CML 15.0001 issue: 11	IECEX CML 15.0001 issue: 12
IECEX CML 15.0068 issue: 0	IECEX CML 15.0068 issue: 1	IECEX CML 15.0068 issue: 2
IECEX CML 15.0068 issue: 3	IECEX CML 15.0068 issue: 4	IECEX CML 15.0068 issue: 5
IECEX CML 15.0068 issue: 6	IECEX CML 15.0068 issue: 7	IECEX CML 15.0068 issue: 8
IECEX CML 15.0068 issue: 9	IECEX CML 16.0052 issue: 0	IECEX CML 16.0052 issue: 1
IECEX CML 16.0052 issue: 2	IECEX CML 16.0052 issue: 3	IECEX CML 16.0052 issue: 4
IECEX CML 16.0052 issue: 5	IECEX CML 16.0052 issue: 6	IECEX CML 17.0074 issue: 0
IECEX CML 17.0074 issue: 1	IECEX CML 17.0074 issue: 2	IECEX CML 17.0074 issue: 3
IECEX CML 17.0120 issue: 0	IECEX CML 17.0120 issue: 1	IECEX CML 17.0135 issue: 0
IECEX CML 17.0135 issue: 1	IECEX CML 18.0087 issue: 0	IECEX CML 18.0087 issue: 1
IECEX CML 21.0037 issue: 0	IECEX CML 21.0038 issue: 0	



IECEX Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR13.0018/09**

Page 2 of 2

Comments: