



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/SIR/QAR13.0018/14	Page 1 of 2
QAR Free Ref. No.:	80273606/80273607/80273608	Status: Issued
Details of change:	Recertification Audit	Date of issue: 2025-12-04
Location(s) audited:	Raytec Limited Unit 15 Wansbeck Business Park Rotary Parkway Ashington Northumberland NE63 8QW United Kingdom	Valid until: 2029-01-07 Audit date: 2025-11-19
Issuing ExCB:	CSAE - CSA Group Testing UK Ltd	
Manufacturer:	Raytec Limited Unit 15 Wansbeck Business Park Rotary Parkway Ashington Northumberland NE63 8QW	
Location of Manufacturer:	United Kingdom	
Product information:	Luminaires, Lamps and Accessories	
Type of protection:	Ex e, m, t, d, nR, ia	
Related QARs:	GB/SIR/QAR13.0018/00 GB/SIR/QAR13.0018/03 GB/SIR/QAR13.0018/06 GB/SIR/QAR13.0018/09 GB/SIR/QAR13.0018/12 GB/SIR/QAR13.0018/01 GB/SIR/QAR13.0018/04 GB/SIR/QAR13.0018/07 GB/SIR/QAR13.0018/10 GB/SIR/QAR13.0018/13 GB/SIR/QAR13.0018/02 GB/SIR/QAR13.0018/05 GB/SIR/QAR13.0018/08 GB/SIR/QAR13.0018/11	

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEX CML 14.0001 issue: 0	IECEX CML 14.0001 issue: 1	IECEX CML 14.0001 issue: 2
IECEX CML 14.0001 issue: 3	IECEX CML 14.0001 issue: 4	IECEX CML 14.0001 issue: 5
IECEX CML 14.0001 issue: 6	IECEX CML 14.0001 issue: 7	IECEX CML 14.0001 issue: 8
IECEX CML 14.0001 issue: 9	IECEX CML 14.0001 issue: 10	IECEX CML 14.0001 issue: 11
IECEX CML 14.0001 issue: 12	IECEX CML 14.0001 issue: 13	IECEX CML 14.0001 issue: 14
IECEX CML 14.0001 issue: 15	IECEX CML 14.0001 issue: 16	IECEX CML 14.0001 issue: 17
IECEX CML 15.0001 issue: 0	IECEX CML 15.0001 issue: 1	IECEX CML 15.0001 issue: 2
IECEX CML 15.0001 issue: 3	IECEX CML 15.0001 issue: 4	IECEX CML 15.0001 issue: 5
IECEX CML 15.0001 issue: 6	IECEX CML 15.0001 issue: 7	IECEX CML 15.0001 issue: 8
IECEX CML 15.0001 issue: 9	IECEX CML 15.0001 issue: 10	IECEX CML 15.0001 issue: 11
IECEX CML 15.0001 issue: 12	IECEX CML 15.0001 issue: 13	IECEX CML 15.0001 issue: 14
IECEX CML 15.0001 issue: 15	IECEX CML 15.0001 issue: 16	IECEX CML 15.0068 issue: 0
IECEX CML 15.0068 issue: 1	IECEX CML 15.0068 issue: 2	IECEX CML 15.0068 issue: 3
IECEX CML 15.0068 issue: 4	IECEX CML 15.0068 issue: 5	IECEX CML 15.0068 issue: 6
IECEX CML 15.0068 issue: 7	IECEX CML 15.0068 issue: 8	IECEX CML 15.0068 issue: 9
IECEX CML 15.0068 issue: 10	IECEX CML 15.0068 issue: 11	IECEX CML 15.0068 issue: 12
IECEX CML 15.0068 issue: 13	IECEX CML 16.0052 issue: 0	IECEX CML 16.0052 issue: 1
IECEX CML 16.0052 issue: 2	IECEX CML 16.0052 issue: 3	IECEX CML 16.0052 issue: 4

-- Continued on the next page



IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR13.0018/14**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEx CML 16.0052 issue: 5
IECEx CML 16.0052 issue: 8
IECEx CML 17.0074 issue: 0
IECEx CML 17.0074 issue: 3
IECEx CML 17.0074 issue: 6
IECEx CML 17.0135 issue: 0
IECEx CML 17.0135 issue: 3
IECEx CML 18.0087 issue: 1
IECEx CML 21.0037 issue: 0
IECEx CML 21.0037 issue: 3
IECEx CML 21.0038 issue: 2
IECEx CML 23.0094X issue: 1

IECEx CML 16.0052 issue: 6
IECEx CML 16.0052 issue: 9
IECEx CML 17.0074 issue: 1
IECEx CML 17.0074 issue: 4
IECEx CML 17.0120 issue: 0
IECEx CML 17.0135 issue: 1
IECEx CML 17.0135 issue: 4
IECEx CML 18.0087 issue: 2
IECEx CML 21.0037 issue: 1
IECEx CML 21.0038 issue: 0
IECEx CML 21.0038 issue: 3
IECEx CML 23.0150X issue: 0

IECEx CML 16.0052 issue: 7
IECEx CML 16.0052 issue: 10
IECEx CML 17.0074 issue: 2
IECEx CML 17.0074 issue: 5
IECEx CML 17.0120 issue: 1
IECEx CML 17.0135 issue: 2
IECEx CML 18.0087 issue: 0
IECEx CML 18.0087 issue: 3
IECEx CML 21.0037 issue: 2
IECEx CML 21.0038 issue: 1
IECEx CML 23.0094X issue: 0

Comments: